

**YERINGTON MINE SITE
QUALITY ASSURANCE PROJECT PLAN
APPENDIX E**

**FIELD SAMPLING
STANDARD OPERATING PROCEDURES**

TABLE OF CONTENTS

<u>Doc. #</u>	<u>Title</u>	<u>Revision/Date</u>
SOP-01	Environmental Sample Handling	Rev 1 -- 05/05/08
SOP-02	Sample Preservation.....	Rev 3 -- 05/05/08
SOP-03	Field Notes and Documentation.....	Rev 0 -- 06/06/06
SOP-04	Instrument Calibration.....	Rev 2 -- 05/05/08
SOP-05	Equipment Decontamination.....	Rev 0 -- 06/06/06
SOP-06	Investigation-Derived Waste Handling Procedures	Rev 0 -- 06/06/06
SOP-07	Groundwater Monitoring Well Installation and Development	Rev 0 -- 06/06/06
SOP-08	Borehole and Monitor Well Destruction.....	Rev 0 -- 06/06/06
SOP-09	Groundwater Sample Collection	Rev 1 -- 05/05/08
SOP-10	PM10 High Volume Air Sampling.....	Rev 0 -- 06/06/06
SOP-11	Soil Sampling	Rev 0 -- 06/06/06
SOP-12	Field Classification and Description of Soil and Rock.....	Rev 0 -- 06/06/06
SOP-13	Soil Excavation	Rev 0 -- 06/06/06
SOP-14	Utility Clearance	Rev 0 -- 06/06/06
SOP-15	Continuous Particulate Air Sampling.....	Rev 1 -- 03/23/07
SOP-16	Monitor Well Water Level Measurement	Rev 0 -- 02/01/07
SOP-17	Sampling for Hydrologic Tracers.....	Rev 0 -- 02/26/07

TABLE OF CONTENTS (CONTINUED)

<u>Doc. #</u>	<u>Title</u>	<u>Revision/Date</u>
SOP-18	Surface Water Sampling.....	Rev 0 -- 05/15/07
SOP-19	Sediment Sampling.....	Rev 0 -- 05/15/07
SOP-20	Pit Lake Water Level Measurement.....	Rev 0 -- 01/11/08
SOP-21	Pressure Transducer Water Level Monitoring.....	Rev 1 -- 04/28/09
SOP-22	Slug Testing.....	Rev 1 -- 04/28/09